



| VALVE LIFT | DURATION | DURATION @ .050 | GRIND NUMBER | DESCRIPTION | REGRIND | HARDWELD | BILLET |
|---------------|-----------|--------------------|-----------------|---|--------------------|----------|--------|
| .265/.265 | 248°/248° | 214°/214° | 84 | Web Camshafts will restore your cam back to factory specifications. Severe lobe damage can be repaired by hard welding, additional charge will apply. | 40-080 \$384.00 | N/A | N/A |

webcamshafts.com Page 1