



Porsche 356 Super 90 8v

Effective June 2022  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.426/.328	273°/273°	233°/233°	62	Stock profile. We can either repair your original camshaft as long as the lobes are not too far gone and the oil pump slot is in good condition, or we have a new cast blank to purchase.	05-650 \$160.00	N/A	05-652 \$385.00