



Porsche 968 DOHC 16v

Effective December 2020  
 Prices Subject To Change  
 Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
	0°/0°	0°/0°	Stock	Precision grind your cam to factory specifications. Price (Each).	05-610 \$286.00	N/A	N/A
Valve Spring Kit With CrMo Retainers Beehive (Race), Turbo				Race kit includes performance Beehive performance valve springs, bottom cups, and Titanium retainers. OK to .500" valve lift. OK for turbo use. Check ALL clearances! Price Per Set (16).			VC-P10 \$675.00
Install New Cam Gear Intake				Web Cam will replace your broken teeth located on the intake cam if necessary. Price (Each).			05-903 \$350.00
Install New Cam Gear Exhaust				Web Cam will replace your broken teeth located on the exhaust cam if necessary. Price (Each).			05-904 \$350.00

NOTE: Severe lobe damage can be repaired by welding. Please contact us directly for details. Performance profiles available from request.