



BMW R 11 Flat Twin 4v

Effective September 2020
Prices Subject To Change
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.204/.204	238°/238°	208°/208°	1129	We have re-mastered the original profile to restore your cam back to new. Journal work is additional if needed. Hardweld cost may be necessary if the cam is severely worn.	01-140 \$255.00	01-141 \$371.00	N/A

We can repair the cam journals if worn by hard chroming, additional charges will be applied.