



BMW R 51 4v

Effective June 2022
Prices Subject To Change
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.234/.234	257°/257°	215°/215°	1278	We have re-mastered the original profile to restore your cam back to new. Journal work is additional if needed. Hardweld cost may be necessary if the cam is severely worn. Price Per Set (2).	01-120 \$360.00	01-121 \$605.00	N/A

We can repair the cam journals if worn by hard chroming, additional charges will be applied.