



BMW R 71 Flat Twin 4v

Effective October 2020  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.251/.251	256°/256°	215°/215°	1208	We have re-mastered the original profile to restore your cam back to new. Journal work is additional if needed. Hardweld cost may be necessary if the cam is severely worn.	01-080 \$255.00	01-081 \$371.00	N/A
Lifters				Web Camshafts will restore your OEM Lifters back to factory specifications. Price Per Set (4).			RL-B00 \$83.00

We can repair the cam journals if worn by hard chroming, additional charges will be applied.