



Henderson B 8v

Effective June 2022  
 Prices Subject To Change  
 Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.149/.209	202°/240°	171°/209°	1162/1161	We will restore your original OEM cam back to factory specifications. Journals can be repaired if needed, additional cost will apply, or we can put this as a performance profile on the smaller profile. Check ALL clearances!	N/A	21-041 \$540.00	N/A
.120/.184	171°/215°	139°/189°	1429/1430	We will restore your original OEM cam back to factory specifications. Journals can be repaired if needed, additional cost will apply.	N/A	21-051 \$540.00	N/A
Labor Hard Chrome Journals				Web Cam will hardchrome and grind your journals back to factory specifications. Price (Each).			HC-000 \$195.00

NOTE: THE LIFT LISTED HERE IS AT THE CAM ON THE INTAKE