



Austin Healey 3000 MK II / MK III BJ 8 12v

Effective September 2020  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.398/.398	248°/248°	214°/214°	84	We will restore your original OEM cam back to factory specifications.	40-040 \$268.00	N/A	N/A
Lifters Regrind OEM				Web Camshafts will restore your OEM Lifters back to factory specifications. Price Per Set (12).			RL-043 \$120.00