



Land Rover SOHC 8v

Effective June 2023  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
			1883/1884	Web Camshafts will restore your cam back to factory specifications. Additional fee will apply if hardwelding is necessary.	13-000 \$425.00	N/A	N/A