



Mercedes Benz 300 SL Roadster SOHC 12v

Effective March 2023  
Prices Subject To Change  
Without Notice!

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.296/.298			1227/1228	Web Camshafts will restore your cam back to factory Sport specifications. Severe lobe damage can be repaired by hard welding, additional charge will apply We can also can also hardweld all lobes and grind the stock profile into the sport profile. Please advise when sending in your cam for processing.	42-090 \$525.00	42-091 \$975.00	N/A
.283/.274			1515/1516	Web Camshafts will restore your cam back to factory specifications. Severe lobe damage can be repaired by hard welding, additional charge will apply.	42-080 \$525.00	N/A	N/A