



Henderson KJ 8v

Effective November 2022
 Prices Subject To Change
 Without Notice!

| VALVE LIFT | DURATION | DURATION @ .050 | GRIND NUMBER | DESCRIPTION | REGRIND | HARDWELD | BILLET |
|----------------------------|-----------|-----------------|--------------|---|---------|--------------------|--------------------|
| .239/.280 | 233°/228° | 206°/209° | 1167/1168 | We will restore your original OEM cam back to factory specifications. Journals can be repaired if needed, additional cost will apply. | N/A | 21-031 \$540.00 | N/A |
| Labor Hard Chrome Journals | | | | Web Cam will hardchrome and grind your journals back to factory specifications. Price (Each). | | | HC-000 \$205.00 |
| Lifters Regrind OEM | | | | Web Camshafts will restore your OEM Lifters back to factory specifications. Price Per Set (8). | | | RL-020 \$85.00 |

NOTE: THE LIFT LISTED HERE IS AT THE CAM ON THE INTAKE