



Honda VF 500 Interceptor DOHC 16v

Effective September 2020  
Prices Subject To Change  
Without Notice!

Custom profiles available for this model, please call us direct.

VALVE LIFT	DURATION	DURATION @ .050	GRIND NUMBER	DESCRIPTION	REGRIND	HARDWELD	BILLET
.208/.208			1265	Web Camshaft will restore your cam back to factory specifications. Requires Hardwelded Rockers. Price Per Set (4).	N/A	59-771 \$915.00	N/A
Rocker Arm Hardwelded				We will hardweld and precision grind your worn out / new rockers for a longer wearing surface. Recommended with ALL profiles. Price (Each).			HR-H30 \$99.00